


AERIAL ANALYSER VK5JST by SP4JJH(ex sp2jjh)



To avoid over-ranging PIC A/D converter inputs (inaccurate calculations) and also possible A/D input damage, TP2 must never exceed 4.7V. Check at all frequencies with no test cct. load.